

# WASP 9500 (WIRED) LASER SCANNER PROGRAMMING CHART

## 1. RESTORE FACTORY DEFAULTS



\*Restore Defaults

## 2. BEEPER FREQUENCY LOW



Low Frequency

## 3. BEEPER VOLUME



Low Volume



Medium Volume



\*High Volume

## 4. OVERRIDE CAPS LOCK




Override Caps Lock Key

## 5. CONVERT TO ALL UPPER CASE



Convert All to Upper Case

## 6. ENABLE CODE 39 CHECK DIGIT



## 7. SCAN OPTIONS



Scan Options

## 8. DATA + SUFFIX



<DATA> <SUFFIX>

## 9. END OPTIONS



Enter